## **ABS Quality Evaluations**

### **Certificate Of Conformance**

This is to certify that the Quality Management System of:

#### ISQAPAVE TECNOLOGIAS LDA.

Rua Kima Kienda, n.º 146
Bairro da Boavista
Luanda, Luanda
Angola

#### (WITH ADDITIONAL FACILITIES LISTED ON ATTACHED ANNEX)

has been assessed by ABS Quality Evaluations, Inc. and found to be in conformance with the requirements set forth by:

ISO 9001:2015

The Quality Management System is applicable to:

INSPECTION AND SUPERVISION OF BUILDINGS, LABORATORY METROLOGY, FOR FLOW AND VOLUME AND FOR PRESSURE VALVES, NON-DESTRUCTIVE CONTROLS, WELDERS QUALIFICATION AND TRAINING.

INSPEÇÃO E FISCALIZAÇÃO DE CONSTRUÇÕES, METROLOGIA LABORATORIAL, DE CAUDAL E VOLUME E DE VÁLVULAS DE PRESSÃO, CONTROLO NÃO DESTRUTIVO, QUALIFICAÇÃO DE SOLDADORES E FORMAÇÃO.

This certificate may be found on the ABS QE Website (www.abs-qe.com). For certificates issued in the People's Republic of China information may also be verified on the CNCA website (www.cnca.gov.cn).

Certificate No: 45276

Last Expiry Date: 25 June 2023
Original Approval Date: 12 August 2011

Effective Date: 06 September 2023 Expiration Date: 25 June 2026

Revision Date: 18 October 2023

1) ominie I ornsend

Dominic Townsend, President







Validity of this certificate is based on the successful completion of the periodic surveillance audits of the management system defined by the above scope and is contingent upon prompt, written notification to ABS Quality Evaluations, Inc. of significant changes to the management system or components thereof.

ABS Quality Evaluations, Inc. 1701 City Plaza Drive, Spring, TX 77389, U.S.A. Validity of this certificate may be confirmed at www.abs-qe.com/cert validation.

# **ABS Quality Evaluations**

ISO 9001:2015

### **Certificate Of Conformance**

### **ANNEX**

Certificate No: 45276

### ISQAPAVE TECNOLOGIAS LDA.

At Below Facilities:

Facility: Rua Kima Kienda, n.º 146

Bairro Boa Vista Luanda, Luanda Angola

Activity: Gestão do SGQ, Realização do Serviço, RH, Logística QMS Management, Service Realization, HR, Logistics

Facility: Rua Centro de Convenções – Via S8, Complexo Sigma, Edifício C

Luanda, Luanda Angola

Activity: Laboratório / Metrologia Laboratory / Metrology





